



Department of natural resources B. M. "X" square
cut in southwest corner of concrete base of
fireplace located 37' east of lake, 87' west of
center of parking lot, 97' south of boat landing.
Assumed elevation 100.00
Water elevation 89.86
B.M. No. 108-C

EQUIPMENT RECORDING SONAR MAPPED AUGUST 1967
MO. YR.

- TOPOGRAPHIC SYMBOLS
- (B) Brush
 - (PW) Partially wooded
 - (W) Wooded
 - (C) Cleared
 - (P) Pastured
 - (A) Agricultural
 - B.M. Bench Mark
 - Dwelling
 - ⊠ Resort
 - ||||| Steep slope
 - - - Indefinite shoreline
 - ⊞ Marsh
 - Spring
 - Intermittent stream
 - ≡ Permanent inlet
 - ≡ Permanent outlet
 - ⊥ Dam

- LAKE BOTTOM SYMBOLS
- P. Peat
 - Gr. Gravel
 - R. Rubble
 - Br. Bedrock
 - T Submergent vegetation
 - ⊥ Emergent vegetation
 - ≡ Floating vegetation
 - Mk. Muck
 - C. Clay
 - M. Marl
 - Sd. Sand
 - St. Silt
 - % Stumps & Snags

SPECIES OF FISH		
	Abundant	Present
Muskie		
N. Pike	X	
Walleye		
L.M. Bass		X
S.M. Bass		
Panfish	X	
Trout		

60.98 ACRES WITH ISLANDS
AREA 59.59 ACRES
UNDER 3FT. 41.09 %
OVER 20FT. 15.32 %
VOLUME 797.5 ACRE FT.
TOTAL ALK. 30 P.P.M.
SHORELINE 1.8 MILES
MAX. DEPTH 23 FEET

Access Access with Parking Boat Livery
Field work by C. Busch, G. Winter, L. Sather Drawn by R. Ripp

Source: Wisconsin Department of Natural Resources 608-266-2621
Chelsea Lake – Taylor County, Wisconsin DNR Lake Map
Date – Aug 1967 - Historical Lake Map - Not for Navigation
A Public Document - Please Identify the Source when using it.